

## DART-MX8M-MINI Yocto Sumo v1.5 release notes

Based on release	Yocto: Poky 2.5, BSP: NXP Sumo BSP L4.14.78-1.0.0_ga, Linux: Freescale imx_4.14.78-1.0.0_ga
Nature of release	Variscite Yocto Sumo i.MX8M Mini Release V1.5
Date	8/27/2019
Supported platform	DART-MX8M-MINI
SOM revision	v1.0 and higher
Carrier board revision	V1.1 and higher
Variscite BSP git	<a href="https://github.com/varigit/meta-variscite-imx">https://github.com/varigit/meta-variscite-imx</a>
Variscite BSP branch	sumo-imx-4.14.78-var01
Variscite BSP commit ID	a32fdaa9240dbde44779b7d004929e246fe7baed
Kernel git	<a href="https://github.com/varigit/linux-imx">https://github.com/varigit/linux-imx</a>
Kernel branch	imx_4.14.78_1.0.0_ga_var01
Kernel commit ID	7808f06d8af265406a4e50d3f2517b44b2e8e239
U-Boot git	<a href="https://github.com/varigit/uboot-imx">https://github.com/varigit/uboot-imx</a>
U-Boot branch	imx_v2018.03_4.14.78_1.0.0_ga_var01
U-Boot commit ID	ddc95a6e5b319d6a649a81a5fc5a26ca3c117659
File System build system	Yocto Sumo
Recovery SD card link	<a href="http://dart-mx8mm-recovery-sd.v15.img.gz">dart-mx8mm-recovery-sd.v15.img.gz</a>
<b>Change list</b>	<b>Description</b>
<a href="#">Release 1.5</a>	
<b>Skip WiFi init if WiFi module is not assembled</b>	avoid long delays on boot
<b>Added support for Microchip mcp2517fd CAN FD</b>	
<a href="#">Release 1.4</a>	
<b>Added U-Boot and kernel support for passing kernel CMA size via kernel command line</b>	Instead of defining CMA size in kernel DTS, pass it via kernel command line
<b>Fixed GPU driver crash on SOMs with 4GB of RAM</b>	GPU driver should not access physical addresses above 4GB
<b>Changed GPU DRAM area size</b>	Changed area size from 2GB to 3GB. Fixes Weston problems on SOMs with 4GB of RAM
<a href="#">Release 1.3</a>	
<b>Added U-Boot support for reading DRAM info from EEPROM</b>	Support multiple DRAM sizes and configurations using a single U-Boot image
<a href="#">Release 1.2</a>	
<b>Added Android installation to the recovery SD card</b>	
<a href="#">Release 1.1</a>	
<b>Fixed kernel bug resulting in missing PCIE interrupts</b>	
<b>Fixed kernel bug resulting in PCIE link detection failure</b>	
<b>Fixed kernel bug resulting in WiFi AP creation failure</b>	
<b>Modified DTS to move audio codec to I2C bus 3</b>	Following hardware change