

<b>DART-6UL Yocto Pyro release notes</b>	
<b>Based on release</b>	Yocto: Poky 2.3.1, BSP: FSL Community BSP 2.3.1, Linux: Freescale rel_imx_4.1.15_2.0.0_ga
<b>Nature of release</b>	New FSL Community Yocto Pyro version release
<b>Release git</b>	<a href="https://github.com/varigit/variscite-bsp-platform">https://github.com/varigit/variscite-bsp-platform</a>
<b>Release tag</b>	pyro-fsl-4.1.15-mx6-v1.1
<b>Date</b>	10/15/2017
<b>Supported platform</b>	All DART-6UL family
<b>SOM revision</b>	DART-6UL/ULL v1.x / DART-6UL-5G
<b>Carrier board revision</b>	V1.2 and higher
<b>Embedded Linux distribution</b>	Yocto FSL Community BSP Pyro 2.3 based
<b>FSL Community BSP link</b>	<a href="http://freescale.github.io/doc/release-notes/2.3/">http://freescale.github.io/doc/release-notes/2.3/</a>
<b>Kernel git</b>	<a href="https://github.com/varigit/linux-2.6-imx">https://github.com/varigit/linux-2.6-imx</a>
<b>Kernel branch</b>	imx-rel_imx_4.1.15_2.0.0_ga-var02
<b>U-Boot git</b>	<a href="https://github.com/varigit/uboot-imx">https://github.com/varigit/uboot-imx</a>
<b>U-Boot branch</b>	imx_v2015.04_4.1.15_1.1.0_ga_var03
<b>File System build system</b>	Yocto Pyro
<b>Recovery SD card link</b>	<a href="http://pyro-fslc-4.1.15-mx6ul-v1.1.img.gz">pyro-fslc-4.1.15-mx6ul-v1.1.img.gz</a>
<b>Change List</b>	<b>Description</b>
<b>Release v1.1</b>	
<b>Upgraded DART-6UL/DART-6UL-5G WIFI firmware</b>	Upgraded WIFI firmware to Laird release 3.5.5.18
<b>Fixed DART-6UL-5G WIFI power management</b>	Significantly reduced WIFI power consumption is suspend
<b>Fixed SPL on latest i.MX6UL silicon revision</b>	Increased SPL start address by 4KB to workaround boot ROM bug
<b>Release v1.0</b>	
<b>Upgraded DART-6UL WIFI firmware</b>	Upgraded WIFI firmware to fix kernel crashes in AP mode
<b>Upgraded DART-6UL/DART-6UL-5G WIFI Driver</b>	Upgraded WIFI driver to fix kernel crashes in AP mode
<b>Run pulseaudio in system mode</b>	AD2P no longer requires running X server
<b>Added SWUpdate support</b>	