VAR-SOM-MX8X Android P9.0.0_2.0.0 V1.5 release notes

Based on release	Google: Android 9.0.0_r30, NXP BSP: P9.0.0_2.0.0_GA
Nature of release	i.MX Android™ P9.0.0_2.0.0_GA release (general availability)
Release git	https://github.com/varigit/MX6x-android/tree/p9.0.0_2.0.0-ga-var01
Release tag	p9.0.0_2.0.0-ga_var-som-mx8x_v12
Date	3/20/2020
Supported platform	VAR-SOM-MX8X
SOM revision	VAR-SOM-MX8X v1.1 and higher
Carrier board revision	V1.1 and higher
NXP BSP FTP	imx-p9.0.0_2.0.0-ga.tar.gz
Variscite BSP git	https://github.com/varigit/MX6x-android
Variscite BSP branch	p9.0.0_2.0.0-ga-var01
Kernel git	https://github.com/varigit/linux-imx
Kernel branch	p9.0.0_2.0.0-ga_var01
U-Boot git	https://github.com/varigit/uboot-imx
U-Boot branch	imx_v2018.03_4.14.98_2.0.0_ga_var01
File System build system	Android
Recovery SD card link	var-som-mx8x-recovery-sd.v15.img.gz

Changes List	Description
Release 1.5	
U-Boot: Add SPL support	
SCFW & U-Boot: Read DDR configuration from EEPROM	
Generate MAC address for second Ethernet interface	
Release 1.2	
Fixed random WiFi init issue	
Release 1.1	
Added support for VAR-SOM-MX8X	

Known issues	Description
Missing MTP and PTP support	The current ptn5150 driver does not support role management