

DART-MX8M-MINI Yocto Sumo v1.1 release notes	
Based on release	Yocto: Poky 2.5, BSP: NXP Sumo BSP L4.14.78-1.0.0_ga, Linux: Freescale imx_4.14.78-1.0.0_ga
Nature of release	Variscite Yocto Sumo i.MX8M Mini Release V1.1
Date	3/28/2019
Supported platform	DART-MX8M-MINI
SOM revision	v1.0 and higher
Carrier board revision	V1.1 and higher
Variscite BSP git	https://github.com/varigit/meta-variscite-imx
Variscite BSP branch	sumo-imx-4.14.78-var01
Variscite BSP commit ID	01bbe16ed46961cc46333abe783f3c2943831c6b
Kernel git	https://github.com/varigit/linux-imx
Kernel branch	imx_4.14.78_1.0.0_ga_var01
Kernel commit ID	edf873536e486ee083fa52fb73cca0581102a932
U-Boot git	https://github.com/varigit/uboot-imx
U-Boot branch	imx_v2018.03_4.14.78_1.0.0_ga_var01
U-Boot commit ID	4e0c0ca5a3f18df00371ac061c02562049a0f634
File System build system	Yocto Sumo
Recovery SD card link	dart-mx8mm-recovery-sd.v11.img.gz
Change list	Description
Release v1.1	
Fixed kernel bug resulting in missing PCIE interrupts	
Fixed kernel bug resulting in PCIE link detection failure	
Fixed kernel bug resulting in WIFI AP creation failure	
Modified DTS to move audio codec to I2C bus 3	Following hardware change